



Rockwell International  
Energy Systems Group

# SUPPORTING DOCUMENT

GO NO. 07704	S/A NO. 44650	PAGE 1 OF 8	TOTAL PAGES 8	REV LTR/CHG NO SEE SUMMARY OF CHG NC	NUMBER N704TI990037
-----------------	------------------	----------------	------------------	--	------------------------

PROGRAM TITLE  
Decontamination and Disposition of Facilities

DOCUMENT TITLE  
Radiological Survey Results--Release to Unrestricted Use, SRE, Building 041

DOCUMENT TYPE Technical Information	KEY NOUNS Decontamination
--	------------------------------

ORIGINAL ISSUE DATE	REL. DATE 11/9/82	APPROVALS	DATE
---------------------	----------------------	-----------	------

PREPARED BY/DATE J. H. Wallace	DEPT 779	MAIL ADDR T-143	R. J. Tuttle R. J. Tuttle 10/26/82 B. F. Ureda B. F. Ureda 10-2482 C. C. Conners C. C. Conners 10/29/82 J. M. Marzec J. M. Marzec 11/1/82 W. R. McCurnin W. R. McCurnin 11/3/82 M. E. Remley M. E. Remley 11/1/82
-----------------------------------	-------------	--------------------	--

IR&D PROGRAM? YES ☐ NO ☒  
IF YES, ENTER TPA NO.

DISTRIBUTION	ABSTRACT
--------------	----------

*	NAME	MAIL ADDR
*	C. C. Conners	NB02
*	J. M. Harris	T055
*	W. M. McCurnin	T020
*	J. M. Marzec	NB02
*	M. E. Remley	NB13
*	R. J. Tuttle	NB13
*	B. F. Ureda	NB02
*	J. H. Wallace	T034

The results of the radiological survey for Building 041, the SRE Facility, are described. All survey results are below the applicable limits, indicating that this area may be released to unrestricted use.

RESERVED FOR PROPRIETARY/LEGAL NOTICES

THIS REPORT MAY NOT BE PUBLISHED WITHOUT THE APPROVAL OF THE DOE OFFICE OF PATENT COUNSEL

This report was prepared as an account of work sponsored by the United States Government. It is the property of the United States Government and is loaned to your organization; it and its contents are not to be distributed outside your organization. It is not to be used for advertising or promotional purposes, for copying or reproduction, for resale, or for any other purpose without the express written permission of the United States Government. It is not to be used for any purpose that would infringe on the rights of any individual or organization.

779-C.46/paw

\* COMPLETE DOCUMENT  
NO ASTERISK, TITLE PAGE/SUMMARY  
OF CHANGE PAGE ONLY



## CONTENTS

	Page
I. Introduction.....	3
II. Surveys and Results.....	6
A. Removable Contamination.....	6
B. Surface Radiation.....	6
C. Soil Samples.....	6
D. Concrete Samples.....	7
E. Water Samples.....	7
III. Conclusions.....	8

## TABLE

1. Contamination/Radiation Limits.....	7
--	---

## FIGURES

1. SRE Facility.....	4
2. SRE Component Storage, Building 041.....	5





## I. INTRODUCTION

This document covers Building 041, SRE component storage, located west of the main building in the SRE complex. The building is a Butler building structure, approximately 138 ft x 28 ft.


Decontamination and disposition of Building 041 began in August 1982, and the building was available for release for unrestricted use on September 17, 1982. The only major operation performed was scabbling of the floor area.

All radioactive material was packaged for shipment to offsite land burial.





SRL COMPONENT STORAGE  
BUILDING 041





## II. SURVEYS AND RESULTS

### A. REMOVABLE CONTAMINATION

Two hundred smears were taken on surfaces throughout the interior of the building. Results of smear surveys were documented at less than 5 dpm alpha and less than 30 dpm beta-gamma.

All smears were counted for alpha and beta-gamma on a Nuclear Measurements Corporation automatic counting system. This system is checked daily with calibrated sources for efficiency. The background for alpha is 0-1 cpm with an average efficiency factor of 3.6. Background for beta is 25-29 cpm with an average efficiency factor of 3.8. Alpha contamination was not suspected for this area. However, had any occurred, it would have been detected with this counting system.

### B. SURFACE RADIATION

At the conclusion of the D&D effort, a survey was conducted using three survey instruments: a Technical Associates Model CP-7 ion chamber detector, an Eberline Model PRM-5-3 low-energy gamma detector, and a Ludlum Model 12 with a thin window pancake GM detector. The low-energy gamma detector and Ludlum GM detector were used for the faster response and audible output. An average background reading of 0.03 mrad/hr was recorded inside the middle of Building 041, which is a typical reading with this instrument in uncontaminated areas. All readings with the CP-7 were below the Table 1 limit of 0.1 mrad/hr.

### C. SOIL SAMPLES

The area outside Building 041 is covered with asphalt paving; therefore, soil samples were not required.



TABLE 1  
CONTAMINATION/RADIATION LIMITS

---

<u>Removable Contamination</u>
20 dpm/100 cm <sup>2</sup> alpha
100 dpm/100 cm <sup>2</sup> beta
<u>Total Contamination (Removable Plus Fixed)</u>
100 dpm/100 cm <sup>2</sup> alpha
0.1 mrad/hr at 1 cm through a
7 mg/cm <sup>2</sup> absorber

---

D. CONCRETE SAMPLES

After the concrete floor had been scabbled and surveyed with the T/A CP-7, the low-energy gamma detector and the Ludlum GM detector, it was decided concrete samples were not required.

E. WATER SAMPLES

There are no natural or manmade catch basins for water in this area; therefore, water samples were not required.



### III. CONCLUSIONS

In each type of test performed, all samples indicated levels less than those limits prescribed by the decontamination and disposition of facilities program for release for unrestricted use.

All appropriate surveys indicate that current existing radioactivity in the area is below the applicable limits for release for unrestricted use.